



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

NMOC

JUL 08 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-8-19 Operator Cross Timbers API #30-0 39-06687

Property Name Breech E Well No. 87 Location: Unit Section 4 Township 26 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 74 Intermediate ✓ Casing 74 Bradenhead 76

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	0		74		
10 min	0		74		
15 min	0		74		
20 min	0		74		
25 min	0		74		
30 min	0		74		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	✓	Vapors
Surges		
Down to Nothing		
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 74

INTERMEDIATE ✓

REMARKS:

Hard blow to vapors at 6 ReConds - vapors
at 5 min - 10 - 15 - 20 - 25 - 30 - 5 min shut in back

By [Signature]
Production Foreman
(Position)

Witness [Signature]

E-mail address jwaggoner@ctfieldsvcs.com