

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES IDEPARTMIENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

DISTRICT III

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 6/20/19 Operator_ENDURING	RESOURCES IV LLCAPI #30-039-07034
Property Name_RINCON UNIT_Well No156_Location: Unit_M_Section_16_Township_27N_Range_06W_ Well Status(Shut-In or roducing)Initial PSI: Tubing 34 Intermediate //A Casing 59 Bradenhead	
OPEN BRADENHEAD AND INTERMEDIATE TO  PRESSURE  Testing Bradenhead INTERM BH Int Csg Int Csg  TIME 5 min 58	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE  Steady Flow
10 min Ø 59 15 min Ø 59 20 min	Surges  Down to Nothing  Nothing
25 min 30 min	Gas & Water Water
If bradenhead flowed water, check all of the descriptions that apply below:  CLEAR FRESH SALTY SULFUR BLACK  5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE  REMARKS:	
By John Docktor Witness  HSE Tech (Position)  E-mail address Jobby Wedning Resources. Com  JUN 27 2019	