



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/30/19 Operator ENDURING RESOURCES IV LLC API # 30-039-07045

Property Name RINCON UNIT Well No. 081 Location: Unit K Section 17 Township 27N Range 06W

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 86 Intermediate N/A Casing 18 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead	Bradenhead	Bradenhead	INTERM	INTERM	BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	<u>Ø</u>		<u>18</u>			Steady Flow	
10 min	<u>Ø</u>		<u>18</u>			Surges	
15 min	<u>Ø</u>		<u>18</u>			Down to Nothing ☒	
20 min						Nothing	
25 min						Gas ☒	
30 min						Gas & Water	☒
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE N/A

REMARKS: blew down to nothing in approximately
ten seconds

By John Dockter

Witness _____

HSE Tech
(Position)

E-mail address JDockter@EnduringResources.com

6/3/19