

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

7							
Date of Test_	5-15	-2019	Operato	Tator SCHALK DEVELOPMENT API #30-0 39 - 20799			
Property Name Schack 52 Well No. 3 Location: Unit E Section 24 Township 29N Range 50							
Well Status(Shut-In or Producing) Initial PSI: Tubing 174 Intermediate 44 Casing 182 Bradenhead 6							
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH							
Testing BH	BH Int Csg Int Csg				FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE		
TIME 5 min Ø		182		Steady Flow_			
10 min Ø		182					
15 min Ø		182		Down to Noth	ning		
20 min	NA		NA	Nothing	XX	NA	
25 min			. \	Gas			
30 min				Gas & Water_			
Water .							
If bradenhead flowed water, check all of the descriptions that apply below:							
CLEAR FRESH SALTY SULFUR BLACK							
5 MINUTE SHUT-IN PRESSURE BRADENHEAD D INTERMEDIATE NA REMARKS: OPENED BH - NOTHING							
By Scott RODGERS With				Witness		and the second s	
LEASE OPERATOR						NMOCD	
(Positi			¥			KW 22 2	
E-mail address Scott c walshing, net						DISTRICT III	