



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmr.state.nm.us/ocd/District III/3distr.htm](http://emmr.state.nm.us/ocd/District%20III/3distr.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/17/19 Operator Roddy Production API #30-0 39-22319

Property Name Ancada Sicarilla Well No. 1 Location: Unit m Section 2 Township 23 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 39 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>39</u>		
10 min	<u>0</u>		<u>39</u>		
15 min	<u>0</u>		<u>39</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>1</u>
Nothing	
Gas	<u>1</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Puff when first opening bradenhead. Nothing after
5 min. shut in.

By Tim F
Lease Manager
(Position)

Witness _____

E-mail address ttixier@crowquest.com

NMOC

JUN 05 2019

DISTRICT III