



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/15/19 Operator Roddy Production API #30-0 43-20373

Property Name Chasen J. A. D. Well No. 102 Location: Unit D Section 26 Township 23 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 123 Intermediate NA Casing 113 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	Bradenhead		INTERM	BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>113</u>		
10 min	<u>0</u>		<u>113</u>		
15 min	<u>0</u>		<u>113</u>		
20 min					
25 min					
30 min					

Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	<u>/</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Blew gas for about 2 to 3 seconds then nothing.

By Tim Tix
Lease Manager
(Position)

Witness _____

E-mail address ttixier@crowquest.com

NMOC
JUN 05 2019
DISTRICT III