



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 14 AUG 2019 Operator 1116 CORP API # 30-0 39-07169

Property Name SAN JUAN 28-6 Well # 115 Location: Unit N Sec 3 Twn 27 Rge 6

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. _____ Tbg. Inj. Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Pressured annulus up to _____ psi. for _____ mins. Test passed/failed

REMARKS: CAST IRON BRIDGE PLUG WAS SET AT 3929
1000 PSI SPRING 60 MINUTE CLOCK
THE CASING WAS PRESSURED UP TO 620 AND PRESSURE HELD FOR
THE ENTIRE TEST

By Don Sheets (Operator Representative) Witness [Signature] (NMOCD)
Onsite Supervisor (Position)

NMOCD
AUG 15 2019
DISTRICT III
AUG 15 2019
DISTRICT III
Revised 02-11-02