



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

NMOCD

AUG 05 2019

MECHANICAL INTEGRITY TEST REPORT

DISTRICT III

(TA OR UIC)

Date of Test 8/5/2019 Operator Hilcorp Energy API # 30-0 39-23575

Property Name Canyon Largo Unit NP Well # 347 Location: Unit H Sec 1 Twn 24 Rge 7

Land Type:

State _____
Federal X
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. 2.3 Tbg. SI Pres. NA Max. Inj. Pres. NA
Cement Head Pres. 0 Tbg. Inj. Pres. NA
Tubing Pres. NA
Int. Casing Pres. NA

Pressured annulus up to 570 psi. for 30 mins. Test passed/failed

REMARKS: 1000 lbs spring, 1hr clock, 1000 lbs 1hr chart Last Calibrated 3/13/19. Start
0 psi, pressured up to 570 psi @ 5 min on chart. 10 min on chart 570 psi BHD psi,
15 min 570 psi BHD 0 psi, 20 min 570 psi BHD 0 psi, 25 min 568 psi BHD 0 psi,
30 min 568 psi BHD 0 psi, 35 min 568 psi BHD 0 psi, bled back down to 0 psi.

by [Signature]
(Operator Representative)

Witness

[Signature]
(NMOCD)

(Position)

Revised 02-11-02