



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 18-JULY-2019 Operator HILLTOP API #30-0 39-23609

Property Name LINDRITH B Well No. 27 Location: Unit M Section 10 Township 24 Range 3

Well Status(Shut-In or Producing) Initial PSI: Tubing 93 Intermediate 0 Casing 88 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	88	0	88
10 min	0	0	88	0	88
15 min	0	0	88	0	88
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	X
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

OPENED THE BRADENHEAD, AND NOTHING CAME OUT
OPENED THE INTERMEDIATE AND NOTHING CAME OUT

By Jeremy Vigil
NSO
(Position)

Witness [Signature]

E-mail address _____

NMOC

JUL 19 2019

DISTRICT III