



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

NMOCD

AUG 05 2019

DISTRICT III

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 8/5/2019 Operator Hilcorp Energy API # 30-0 39-2365D

Property Name Canyon Largo Unit Well # 308 Location: Unit 6 Sec 5 Twn 24 Rge 6

Land Type:

State _____
Federal X
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. -2.6
Headhead Pres. 0
Tubing Pres. NA
Int. Casing Pres. NA

Tbg. SI Pres. NA
Tbg. Inj. Pres. NA

Max. Inj. Pres. NA

Pressured annulus up to _____ psi. for _____ mins. Test passed/failed failed

REMARKS: 1000 lbs spring, 1 hr clock, 1 hr 1000 lbs chart, last calibrated 3/13/2019.
Casing on a vacuum at start of test, pumped 4.3 bbls to load casing. Start @
0 psi, pressured up to _____ psi @ _____ min on chart. _____ min on chart _____ psi BHT
unable to pressure up, got an injection rate.

(Operator Representative)

Witness Jonathan D. Kelly
(NMOCD)

(Position)

Revised 02-11-02