



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 25-JULY-2019 Operator HILCORP API # 30-0 39-29202

Property Name SAN JUAN 29-7 Well # 550 S Location: Unit ___ Sec 11 Twn 29 Rge 7

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. _____ Tbg. Inj. Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Pressured annulus up to 570 psi. for 10 mins. Test passed/failed

REMARKS: 1000 PSI SPRING, 60 MINUTE CLOCK
THE CASING WAS PRESSURED UP TO 570 PSI AND PRESSURE
FELL TO 560 AND HELD FOR THE LAST 10 MINUTES

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

NMOCD

JUL 29 2019

DISTRICT III

Revised 02-11-02