

**OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
www.state.nm.us/ooc/District/III/2/district.htm**

MMOC

11 2019

DISTRICT XXX

(submit 1 copy to above address)

Well Status (Shut-In or Producing) Initial PSI: Tubing 13 Intermediate N/A Casing 35 Bradenhead 118

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	BRADENHEAD			INTERMEDIATE	
	BH	Int	Csg	Int	Csg
5 min	Ø		49.5		
10 min	Ø		51.1		
15 min	Ø		52.3		
20 min					
25 min					
30 min					
5 min Shut-in	13.2		53.3		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing <i>3 sec</i>	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 13.2 INTERMEDIATE N/A

REMARKS:

REMARKS: No blow down due to sampling. Samples T-4932, C-7087, # BH 7061
whisper at start of test for 3 sec no flow after.

By Eugenia Hamilton
Technician
(Position)

Witness

E-mail address Evgenia.H@perso.irc.uz