



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
http://emrhd.state.nm.us/ocd/District III/3district.htm

NMOCB

JUL 26 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7.25.19 Operator Southland Royalty Co. LLC API # 30-0 45-09315
Property Name McCoid Well No. 13 Location: Unit 22 Section 22 Township 30N Range 13W
Well Status (Shut-In or Producing) Initial PSI: Tubing 170 Intermediate NA Casing 175 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0		176		
10 min	0		177		
15 min	0		178		
20 min	0		179		
25 min	0		180		
30 min	0		181		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<input checked="" type="checkbox"/>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

Nothing when opened Nothing when opened
after 5 min shut-in
6 month test after bradenhead repair

By Vandora Pitt

Witness Monica Cuchling

(Position)

E-mail address _____

Need bradenhead test at
1 year after repair - January 25-
2020