

inspection # IMPK 194955268



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrwd.state.nm.us/ocd/District/873district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-9-19 Operator BPV API #30-0 4511686

Property Name BCU Well No. 233 Location: Unit M Section 27 Township 28N Range 12W

Well Status (Shut-In or Producing) Initial PSI: Tubing _____ Intermediate _____ Casing _____ Bradenhead _____

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	Ø		8.2		
10 min	Ø		8.2		
15 min	Ø		8.2		
20 min	Ø		8.2		
25 min	Ø		8.2		
30 min	Ø		8.2		
5 min shut-in	7.5		8.2		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	<u>Vapor</u>	
Surges		
Down to Nothing	<u>28 sec</u>	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 7.5

INTERMEDIATE N/A

REMARKS:

No blow down due to sampling. Samples T-7066, C-7036, & BH 96844.
Whisper for 28 sec at start of test and vapor after.

By Eugenia Hamilton

Witness _____

Technician
(Position)

E-mail address Eugenia.Hamilton@percine.biz

DISTRICT III