



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-17-19 Operator BPX API # 3044522147

Property Name Florance GC D4A Location: Unit Section Township Range
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 17 Intermediate N/A Casing 49 Bradenhead 32

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>Ø</u>	<u>49</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	Steady Flow	<u>N/A</u>
10 minutes	<u>Ø</u>	<u>49</u>	<u> </u>	<u> </u>	<u> </u>	Surges	<u> </u>
15 minutes	<u>Ø</u>	<u>49</u>	<u> </u>	<u> </u>	<u> </u>	Down to Nothing	<u> </u>
20 minutes	<u>Ø</u>	<u>49</u>	<u> </u>	<u> </u>	<u> </u>	No Flow	<u> </u>
25 minutes	<u>Ø</u>	<u>49</u>	<u> </u>	<u> </u>	<u> </u>	Gas	<u> </u>
30 minutes	<u>Ø</u>	<u>49</u>	<u> </u>	<u> </u>	<u> </u>	Gas and Water	<u> </u>
5 minute SI	<u>2</u>	<u>49</u>	<u> </u>	<u> </u>	<u> </u>	Water	<u> </u>

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 2 Intermediate N/A

REMARKS:

Samples taken: BH-2584, T- 1014, & C- D18. Whisper at start of
test for 38sec down to vapor. Vapor at 5min. No vapor at 10min. No vapor at
15 min. No vapor at 20 min. No vapor at 25 min. No vapor at 30 min. Huff for
2sec at end of 5min shut-in. to vapor. Compressor on site.

By Eugenia Hamilton Witness
Technician

(Position)