NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

NMOCD
JUN 21 2019
DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-20-19 Operator Great Western API #30-0 45-23081

Property Name JE Decker Well No. 3A Location: Unit ___ Section 8 Township 32 Range 11

Well Status(Shut-In or Producing) Initial PSI: Tubing 250 Intermediate N/A Casing 260 Bradenhead 53

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	8		260		
10 min	8		260		
15 min	8		260		
20 min	8		260		
25 min	7		260		
30 min	7		260		

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow	/	
Surges		
Down to Nothing		
Nothing		
Gas	/	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 46 INTERMEDIATE N/A

REMARKS: Had blow when opened for full 30 minute test - need to fix.

By [signature] Witness Monica Kuehling

(Position)

E-mail address _____