



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-13-19 Operator BPX API # 3044523159

Property Name Mudge Ls 45 Location: Unit 11 Section 3 Township 31 Range 11
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing N/A Intermediate N/A Casing 23 Bradenhead 12

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>23</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	Steady Flow		<u>N/A</u>
10 minutes	<u>0</u>	<u>24</u>	<u>1</u>	<u>1</u>	<u>1</u>	Surges		
15 minutes	<u>0</u>	<u>24</u>	<u>1</u>	<u>1</u>	<u>1</u>	Down to Nothing	<u>✓</u>	
20 minutes			<u>1</u>	<u>1</u>	<u>1</u>	No Flow		
25 minutes			<u>1</u>	<u>1</u>	<u>1</u>	Gas		
30 minutes			<u>1</u>	<u>1</u>	<u>1</u>	Gas and Water		
5 minute SI	<u>3</u>	<u>24</u>	<u>1</u>	<u>1</u>	<u>1</u>	Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black DISTRICT III

5 Minute Shut-in Bradenhead 3 Intermediate N/A

REMARKS:

Samples taken: BH-7004 & C-8002. Slim Hole Design. Puff at start of test no flow after Puff after 5min shut-in. BH blew down quick in less than 1 sec.

By Eugenia Hami Hon
Technician

Witness _____

(Position)