



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8 AUG 2014 Operator HILCORP API #30-0 45-23618
Property Name O'SHEA Well No. 1M Location: Unit F Section 3 Township 31 Range 13
Well Status(Shut-In or Producing) Initial PSI: Tubing 160 Intermediate N/A Casing 140 Bradenhead 137

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	.1	N/A	140		
10 min	.1		140		
15 min	.1		140		
20 min	.1		140		
25 min	.1		140		
30 min	.1		140		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	☒	
Surges		
Down to Nothing		
Nothing		
Gas	☒	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1.5 INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND IT FLOWED FOR THE ENTIRE TEST.

REQUESTED A GAS ANALYSIS AND WELLBORE SCHEMATIC

By [Signature]

Witness [Signature]

(Position)

E-mail address _____

NMOC
AUG 08 2014
DISTRICT III