



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6179
<http://emmrnd.state.nm.us/ocd/District/823distric.htm>

insp# IMPK194933335

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-9-19 Operator BPX API #30-0 4524645

Property Name GCV Well No. 217E Location: Unit D Section 13 Township 28N Range 12W

Well Status (Shut-In or Producing) Initial PSI: Tubing 31 Intermediate N/A Casing 29 Bradenhead 168

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	Ø		29.7			
10 min	Ø		28.8			
15 min	Ø		28.2			
20 min						
25 min						
30 min						
5 min shut-in	Ø		27.5			

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing 47 sec

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE N/A

REMARKS:

No blowdown due to sampling. Samples BH-7000, C-7052, & 2005.
Pump Jack running, casing flowing, whisper at start of test.

By Eugenia Hamilton
Technician
(Position)

Witness _____

E-mail address EugeniaH@percoine.biz

JUL 11 2019

DISTRICT III