

Inspection IMPK 195133558



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6170 FAX: (505) 334-6170
<http://emrwd.state.nm.us/ocd/District/IMPdistrict.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-17-19 Operator BPX API #30-0 4525234

Property Name BCU Well No. 133E Location: Unit C Section 17 Township 24N Range 12W

Well Status (Shut-In or Producing) Initial PSI: Tubing 43 Intermediate N/A Casing 45 Bradenhead 144

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	Ø		53.0			
10 min	Ø		53.6			
15 min	Ø		54.1			
20 min						
25 min						
30 min						
5 min shut-in	1.8		54.6			

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing	2m 43sec		
Nothing			
Gas			
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1.8 INTERMEDIATE N/A

REMARKS: No blow down due to sampling. Whisper @ start of test for 2min 43sec
down to nothing. Casing closed. Samples BH-7098, T-8003, & 7201

By Eugenia Hamilton
Technician
(Position)

Witness _____

E-mail address EugeniaH@percointc.biz

JUL 11 2019

DISTRICT III