



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8 AUG 2019 Operator HILCORP API #30-0 45-32689

Property Name VALANCE 33 Well No. 2 Location: Unit 13 Section 33 Township 31 Range 13

Well Status(Shut-In or Producing) Initial PSI: Tubing 330 Intermediate N/A Casing 33 Bradenhead 160

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME	0.5	N/A	33		
5 min	0.5		33		
10 min	0.5		33		
15 min	0.5		33		
20 min	0.5		33		
25 min	0.5		33		
30 min	0.5		33		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	X	
Surges		
Down to Nothing		
Nothing		
Gas	X	
Gas & Water	X	
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 21 INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND WATER FLOWED FOR THE ENTIRE TEST
MADE 1 GALON OF WATER EVERY 5 MINUTES.

REQUESTED A GAS ANALYSIS AND WELL BORE SCHEMATIC AND A WATER ANALYSIS.

By [Signature]

Witness [Signature]

(Position)

E-mail address _____

WMOC

AUG 08 2019

DISTRICT III