



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/IV3/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-24-19 Operator Benson Montin Greer API #30-0 39-06026

Property Name CCU Well No. 05 Location: Unit B Section 18 Township 25N Range 1E

Well Status (Shut-In or Producing) Initial PSI: Tubing 98 Intermediate N/A Casing 150 Bradenhead 5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM		
	BH	Bradenhead Int	Csg	Int	Csg	
5 min	5		150			
10 min	0		150			
15 min	0		151			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing	✓		
Nothing	✓		
Gas			
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS: Braden Head Had 5^{PSI} blew down in 10 seconds stayed at 0^{PSI}
for duration of the Test

By Benson Montin Greer
Lease operator
(Position)

Witness _____

E-mail address _____

NMOC

AUG 05 2019

DISTRICT III