



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/8/19 Operator ENDURING RESOURCES IV LLC API #30-039-06917

Property Name RINCON UNIT Well No. 135 Location: Unit B Section 29 Township 27N Range 06W

Well Status (Shut-In or Producing) Initial PSI: Tubing 28 Intermediate 4 Casing 45 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	Ø	3	45	Ø	44
10 min	Ø	3	45	Ø	44
15 min	Ø	3	44	Ø	44
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	✓
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE Ø

REMARKS: Intermediate blew down to nothing in approx
twenty seconds
after 5 min shut in, intermediate read no pressure, but puffed for 3 secs.

By J Dockter
HSE Tech
(Position)

Witness _____

E-mail address JDockter@EnduringResources.com

NMOCOD
AUG 14 2019
DISTRICT III
8/13/19