



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/11/19 Operator ENDURING RESOURCES IV LLC API #30-039-07083

Property Name RINCON UNIT Well No. 079 Location: Unit A Section 17 Township 27N Range 06W

Well Status (Shut-In or Producing) Initial PSI: Tubing 46 Intermediate Ø Casing 50 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	Ø	Ø	52	Ø	53
10 min	Ø	Ø	52	Ø	53
15 min	Ø	Ø	52	Ø	53
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø INTERMEDIATE Ø

REMARKS:

Bad
intermediate puffed down to nothing after four seconds

By John Dockter

Witness _____

HSE Tech

(Position)

E-mail address JDockter@EnduringResources.com

JUL 15 2019

DISTRICT III

7/15/19