NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-24-19 Operator Benson Montin Greer API #30-0 39-20372

Property Name COU Well No. 18 Location: Unit C Section 5 Township 25 N Range 1E

Well Status(Shut-In or Producing) Initial PSI: Tubing 9 Intermediate N/A Casing 15 Bradenhead 11

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	11		15		
10 min	0		15		
15 min	0		15		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing	✓	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR____ FRESH____ SALTY____ SULFUR____ BLACK____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE____

REMARKS: Bradenhead Had 11 PSI It blew Down 58 seconds and stayed at 0 PSI for duration of test

By Benni Velasquez

Lease operator
(Position)

Witness____

E-mail address____

NMOCD
AUG 05 2019
DISTRICT III