



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/26/19 Operator ENDURING RESOURCES IV LLC API # 30-039-21079

Property Name PAUL WILLIAMS Well No. 003 Location: Unit F Section 35 Township 26N Range 06W

Well Status (Shut-In or Producing) Initial PSI: Tubing 127 Intermediate N/A Casing 126 Bradenhead <1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>Ø</u>		<u>127</u>		
10 min	<u>Ø</u>		<u>127</u>		
15 min	<u>Ø</u>		<u>128</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	☒	
Nothing		
Gas	☒	
Gas & Water		
Water		

NMOCD

JUL 30 2019

DISTRICT III

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD <1

INTERMEDIATE N/A

REMARKS:

- bradenhead blew down for approx 10 seconds

By John Dockter
HSE Tech
(Position)

Witness _____

E-mail address JDockter@EnduringResources.com

7/30/19