

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

## BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test7-23-19Operator: EnerVest Operating, LLC API # 30-039-22179	
Property Name: jic cont 146 Well No 10e Location: Unit e Section: 9 Township: 25n_Range: 5w	
Well Status (Shut-In or Producing) Initial PSI: Tub	oing 65 Intermediate Casing 80 Bradenhead 0
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE  Testing Bradenhead INTERM  BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 0 80	Steady Flow
10 min080	Surges
15 min 0 80	Down to Nothingx_
20 min	Nothing
25 min	Gas
30 min	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY	SULFURBLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD_0 INTERMEDIATE	
REMARKS:0 on braiding head _slight blow	
By orel browning	Witness
Lease Operator 3(Position)	NMOGD
(* *******)	1111 2 2 2000
	DISTIRUCT IIII