



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOC

AUG 07 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/1/19 Operator ENDURING RESOURCES IV LLC API #30-039-31224

Property Name: NE CHACO COM Well No: 184H Location: Unit A Section 13 Township 23N Range 07W

Well Status(Shut-In or Producing) Producing Initial PSI: Tubing 43 Intermediate N/A Casing 193 Bradenhead <1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	Ø		192		
10 min	Ø		188		
15 min	Ø		196		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing	✓	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE N/A

REMARKS:

blew down, test after 10:53am, 8/1/19,
bradenhead blew down in approx five seconds

By John Dockett
HSE Tech
(Position)

Witness _____

E-mail address JDockett@EnduringResources.com

8/6/19