



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/2/19 Operator Enduring Resources LLC API #30-039-31228
Property Name NE Chaco Com Well No. 185H Location: Unit 1 Section 18 Township 23N Range 6W
Well Status (Shut-In or Producing) Initial PSI: Tubing 44 Intermediate N/A Casing 162 Bradenhead 11

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead	INTERM		
		Inf	Csg	Inf	Csg
TIME					
5 min	<u>Ø</u>		<u>154</u>		
10 min	<u>Ø</u>		<u>163</u>		
15 min	<u>Ø</u>		<u>157</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	☒	
Nothing		
Gas	☒	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 41 INTERMEDIATE N/A

REMARKS: bradenhead blew down in approx five seconds

By [Signature]
HSE Tech
(Position)

Witness _____

E-mail address JD DOKAR @ Enduring Resources.com

NMOCD
AUG 14 2019
DISTRICT III

8/13/19