



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnr.state.nm.us/ocd/District III/3district.htm>

NMOC

AUG 07 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/1/19 Operator ENDURING RESOURCES IV LLC API #30-039-31245

Property Name: NE CHACO COM Well No: 204H Location: Unit I Section 13 Township 23N Range 07W

Well Status(Shut-In or Producing) Producing Initial PSI: Tubing 27 Intermediate N/A Casing 351 Bradenhead 41

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	Ø		354		
10 min	Ø		353		
15 min	Ø		352		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE N/A

REMARKS:

Shut down test after 9:45am, 8/1/19  
- Bradenhead puffed down to nothing in two seconds

By John Decker  
HSE Tech  
(Position)

Witness \_\_\_\_\_

E-mail address JDecker@EnduringResources.com

8/6/19