



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

NMOCD

AUG 07 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/31/19 Operator ENDURING RESOURCES IV LLC API #30-039-31252

Property Name: NE CHACO COM Well No: 177H Location: Unit D Section 06 Township 23N Range 06W

Well Status (Shut-In or Producing) Initial PSI: Tubing 69 Intermediate N/A Casing 352 Bradenhead <1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
TIME								
5 min	<u>Ø</u>		<u>343</u>				Steady Flow	
10 min	<u>Ø</u>		<u>350</u>				Surges	
15 min	<u>Ø</u>		<u>353</u>				Down to Nothing <u>✓</u>	
20 min							Nothing	
25 min							Gas <u>✓</u>	
30 min							Gas & Water	
							Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE N/A

REMARKS:

test after 11:30am, 7/31/19
- bradenhead blew down in approx two seconds

By

John Dockter
HSE Tech
(Position)

Witness

E-mail address

JDockter@EnduringResources.com

8/6/19