



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/6/19 Operator ENDURING RESOURCES IV LLC API #30-039-31340

Property Name: MC 8 COM Well No: 410H Location: Unit N Section 07 Township 23N Range 07W

Well Status(Shut-In or Producing) Initial PSI: Tubing III Intermediate N/A Casing 562 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 min	Ø		562			Steady Flow	
10 min	Ø		563			Surges	
15 min	Ø		563			Down to Nothing	
20 min						Nothing	✓
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE N/A

REMARKS: - blew down on 8/5/19, test after 2:20pm, 8/6/19

By [Signature] Witness _____
HSE Tech
(Position)

E-mail address JDokter@EnduringResources.com

NMOC
AUG 16 2019
DISTRICT III
8/13/19