



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/6/19 Operator ENDURING RESOURCES IV LLC API #30-043-21148

Property Name: CHACO 2206 16A Well No: 221H Location: Unit A Section 16 Township 22N Range 06W

Well Status (Shut-In or Producing) Initial PSI: Tubing 87 Intermediate 8 Casing 16 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME	Ø	8	15	Ø	15
5 min	Ø	8	15	Ø	15
10 min	Ø	8	15	Ø	15
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE Ø

REMARKS:

- blew down on 8/5/19, test after 1:pm on 8/6/19

- bradenhead had a two second puff down to nothing

- intermediate blew down to nothing in approx 60 seconds

By John Daxter

Witness _____

(Position)

E-mail address JDaxter@EnduringResources.com

NMOC
AUG 14 2019
DISTRICT III

8/13/19