



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

NMOCd

JUL 08 20

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-8-19 Operator Cross Timbers Energy LLC API #30-039066470000

Property Name Breech E Well No. 109 Location: Rio Arriba County
Unit M Section 03 Township 26N Range 06W

Well Status (Shut-In or Producing) Initial PSI: Tubing 103 Intermediate 1/A Casing 103 Bradenhead 81

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	BH	Bradenhead Int	Csg	INTERM Int	Csg	BRADENHEAD	INTERMEDIATE
TIME							
5 min	1		103			Steady Flow	1 0.4/0.5
10 min	0		103			Surges	
15 min	0		104			Down to Nothing	
20 min	0		104			Nothing	
25 min	0		104			Gas	1
30 min	0		105			Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 2

INTERMEDIATE 1/A

REMARKS:

down to med/light blow at 2 seconds - light
5-10-15-20-25-30 - Back up at 5 min shut-in -

By Jeff Wagoner
Production Foreman
(Position)

Witness Mona Kuchling

E-mail address jwaggoner@ctfieldservices.com