



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrmd.state.nm.us/ocd/District IU3/district.htm](http://emrmd.state.nm.us/ocd/District%20IU3/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-15-19 Operator RL Bayless API #30-0 39-21741
Property Name Schalk 29-4 Well No. 411 Location: Unit 5-152 Section 23 Township 29 Range 4w
Well Status (Shut-In or Producing) Initial PSI: Tubing 960 Intermediate Casing 960 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	0		960		
10 min	0		960		
15 min	0		960		
20 min	0		960		
25 min	0		960		
30 min	0		960		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 PSI INTERMEDIATE

REMARKS:

Zero psi @ 5-10-15-20-25-30 minutes

By Adrian Lopez

Witness

paper
(Position)

E-mail address

*Received in
e-mail 8/5/19*