



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emrld.state.nm.us/ocd/District III/3district.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

39-24278

Date of Test 7-MAY-2019 Operator SUTHLAND API #30-0 39-24287

Property Name Carracas Unit 27A Well No. 82 Location: Unit Section 27 Township 32 Range S

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 19 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Table with columns: Testing, PRESSURE (Bradenhead: BH, Int, Csg; INTERM: Int, Csg), TIME (5 min to 30 min). Data includes handwritten values like 0, N/A, 19.

Table with columns: FLOW CHARACTERISTICS (BRADENHEAD, INTERMEDIATE). Rows include Steady Flow, Surges, Down to Nothing, Nothing, Gas, Gas & Water, Water. Includes handwritten 'X' and 'N/A'.

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT.

By [Signature] Lease Operator (Position)

Witness [Signature]

E-mail address

NMOCB APR 07 2019 DISTRICT III