

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test_	8/23/19	_Operator_ENDURIN	IG RESOURCES IV LLC_AI	PI #30-039-31278
Property Name: NE CHACO COM Well No: 197H Location: Unit E Section 08 Township 23N Range 06W  Well Status(Shut-In or Producing) Initial PSI: Tubing 21/2/2 Intermediate 1/2/2 Casing 23 Bradenhead				
Testing	PRESSU Bradenhead	RE INTERM		UALLY FOR 15 MINUTES EACH  CHARACTERISTICS EAD INTERMEDIATE
TIME 5 min 10 min 20 min 25 min 30 min	Int Csg 23 23 23	Int Csg	Steady Flow Surges  Down to Nothing  Nothing  Gas  Gas & Water	NMOCD
Water  If bradenhead flowed water, check all of the descriptions that apply below:  CLEAR FRESH SALTY SULFUR BLACK				
S MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE MARKS:				
By Jacks  HSE TO  (Position			/itness	
E-mail address	JANEX DES PO	Enden g Ratera	Es. Com	8-24-19