



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT
NMOC

SEP 03 2019

DISTRICT III

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9.3.19 Operator Hilcorp Energy API #30-0 45.28549
Property Name San Juan 32.7th SW Well No. 301 Location: Unit 34 Section 34 Township 32 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 852 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	0	0	0
10 min	0	0	0	0	0
15 min	0	0	0	0	0
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH - Hard puff when opened. Nothing when opened after 5 min shut in. Int - Med light blow to head in 24 seconds. Puff when opened after 5 min shut in.

By Interwitness R

Witness Momca Kuehling Shut in

(Position)

E-mail address _____