



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District II/3district.htm](http://emnr.state.nm.us/ocd/District%20II/3district.htm)

111 10181510

6102 50

0300NN

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9.5.19 Operator Hilcorp Energy API #30-0 45-34454
Property Name Canyon SW Well No. 1 Location: Unit 12 Section 35 Township 26 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 961 Intermediate NA Casing 946 Bradenhead 537

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	0		948			
10 min	0		945			
15 min	0		945			
20 min	0		945			
25 min	0		944			
30 min	0		944			

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	/
Nothing	
Gas	
Gas & Water	/
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1

INTERMEDIATE NA

REMARKS:

Well is shut-in due to tubing communicating with production casing - Puff with water to top of pipe - Water at top of pipe full 30 minute test - water

By Robert J. Lisk
SW Operator
(Position)

Witness Norma Kuehling Squat & hold at top of pipe

E-mail address _____