



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6176 FAX: (505) 334-6170

<http://emnr.state.nm.us/ocd/District/III3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-19-19 Operator Dominion Prod API #30-0 31-05193

Property Name HSU Well No. 89 Location: Unit B Section 1 Township 17 Range 9

Well Status (Shut-In) or Producing Initial PSI: Tubing 0 Intermediate Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>				
10 min	<u>0</u>				
15 min	<u>0</u>				
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing ☒	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS:

opened BTH and had vacuum, died
around 20 secs, had short vacuum after
5 min shut in

By [Signature]

Witness

(Position)

E-mail address

NMOC

SEP 11 2019

DISTRICT III