



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District II/3district.htm](http://emnr.state.nm.us/ocd/District%20II/3district.htm)

NMOC

SEP 12 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9.11.19 Operator Reliable Prod. API #30-0 39-05636

Property Name Bolack Well No. 1 Location: Unit 1 Section 1 Township 24 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 50 Intermediate 1/A Casing 62 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Bradenhead Int	Csg	Int	Csg	
TIME	<u>0</u>		<u>62</u>			
5 min	<u>0</u>		<u>62</u>			
10 min	<u>0</u>		<u>62</u>			
15 min	<u>0</u>		<u>62</u>			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/A

REMARKS:

Nothing when opened. Nothing when
opened after 5 min shut in

By Archie Fzane

Witness Mona Tuckling

(Position)

E-mail address _____