



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

NMOC

NMOC

OCT 16 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10.16.19 Operator Cross Timbers API #30-0 39-06687

Property Name Breech E Well No. 87 Location: Unit Section 4 Township 26 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 77 Intermediate Casing 77 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		77		
10 min	0		77		
15 min	0		77		
20 min	0		77		
25 min	0		77		
30 min	0		77		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
<u>up</u> Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

sucked when opened. this well has had all seals replaced
nothing when opened after 5 min shut-in

By Jeff Waggoner
Production Foreman
(Position)

Witness Monica Kuchling
Test 6-months. 1 year

E-mail address jwaggoner@ctfield.sucs.com