



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmrnd.state.nm.us/ocd/District III3district.htm](http://emmrnd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-10-19 Operator NMJO Operating Co API # 30-03922860052

Property Name Gavilan Well No. 1 Location: Unit A Section 26 Township 25N Range 2W

Well Status (Shut-In or Producing) Initial PSI: Tubing 180 Intermediate X Casing 245 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	1	245		
10 min	0	1	245		
15 min	0	1	245		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE _____ BRADENHEAD 0 INTERMEDIATE _____

REMARKS: Slight Blow

By Cary Davis
in so
(Position)

Witness _____

E-mail address _____

NMOCD

OCT 17 2019

DISTRICT III