



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrwd.state.nm.us/ocd/District III3district.htm](http://emrwd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-16-19 Operator NM30 Operating Co API #30-0 3923192
Property Name Gavilan Well No. 3 Location: Unit E Section 26 Township 25N Range 2W
Well Status (Shut-In or Producing) Initial PSI: Tubing 1200 Intermediate 4 Casing 1200 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	0	0	1200	0	1200
10 min	0	0	1200	0	1200
15 min	0	0	1200	0	1200
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

B.H. Vacuum Blow down in 5 seconds
Interm Blow down in 4 second

By Cary Davis
MSO
(Position)

Witness _____

E-mail address _____

NMOCD

OCT 07 2019

DISTRICT III