NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

NMOCD

SEP 12 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9.11.19 Operator Reliable Prod. API #30-0 39-23542

Property Name Johns Dasheto Well No. 4 Location: Unit ___ Section 12 Township 24 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 70 Intermediate N/A Casing 85 Bradenhead 65

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0		80		
10 min	0		80		
15 min	0		80		
20 min	0		80		
25 min	0		80		
30 min	0		80		

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow	✓	
Surges		
Down to Nothing		
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 81 INTERMEDIATE N/A

REMARKS: Hard blow when opened to Med blow at 1 min
5-10-15-20-25-30-

By Adrian Lozano

(Position)

E-mail address

Witness Monica Kuehling

Gas Samples - BH, Casing
analysis due in 6 weeks
tubing would have oil