



NEW MEXICO DEPARTMENT OF
NATURAL RESOURCES

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/27/19 Operator Blackhawk energy Corp API #30-0 39-24253
Property Name JIC 464 Well No. 8 Location: Unit K Section 29 Township 30N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 384 Intermediate Casing 413 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>413</u>		
10 min	<u>0</u>		<u>413</u>		
15 min	<u>0</u>		<u>413</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	☒
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

BH showed 0-psi on gauge and nothing through out Test.
casing held @ 413 psi through out Test
BH showed 0-psi after 5 min shut-in, nothing else.

By Robert Talamante
Plant/lease operator
(Position)

Witness

E-mail address rtalamante@blackhawkenergy.com

SEP 10 2019
DISTRICT III