



BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/20/19 Operator BlackHawk Energy API #30-0 39-24257

Property Name Jicarilla 452 Well No. 4 Location: Unit D Section 5 Township 29N Range 3W

Well Status(Shut-In or Producing) Initial PSI: Tubing 26 Intermediate N/A Casing 37 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Table with columns: Testing TIME, Bradenhead (BH, Int, Csg), INTERM (Int, Csg). Rows for 5, 10, 15, 20, 25, 30 minutes. Values: 0, 37, 37, 37.

Table with columns: FLOW CHARACTERISTICS (BRADENHEAD, INTERMEDIATE). Rows: Steady Flow, Surges, Down to Nothing, Nothing (marked with X), Gas, Gas & Water, Water.

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Opened Bradenhead valve 8/16/19 nothing was on it.

By [Signature] Lease Operator

(Position)

Witness

E-mail address dsnell@blackhawkenergycorp.com

NMOC D
SEP 10 2019
DISTRICT III