



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District II/3district.htm](http://emnr.state.nm.us/ocd/District%20II/3district.htm)

NMOC

SEP 12 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9.11.19 Operator Reliable Prod. API #30-0 39-25374
Property Name Blue Mesa Well No. 2 Location: Unit Section 12 Township 24 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 17 Intermediate 1/A Casing 20 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>20</u>		
10 min	<u>0</u>		<u>18</u>		
15 min	<u>0</u>		<u>18</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	<u>✓</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Light blow to dead at 5 seconds. Started producing at 10 min - Nothing when opened after 5 min Shut in

By Adrian Lopez

Witness Monica Kuehling

(Position)

E-mail address