



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 9.9.19 Operator Hilcorp Energy API # 30-0 39-25465

Property Name Jillson Federal SW Well # 1 Location: Unit 8 Sec 8 Twn 24 Rge 3

Land Type:

State
Federal
Private
Indian

Well Type:

Water Injection
Salt Water Disposal ✓
Gas Injection
Producing Oil/Gas
Pressure observation

NMOCD
SEP 10 2019
DISTRICT III

Temporarily Abandoned Well (Y/N) (N) TA Expires:

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 0
Int. Casing Pres. N/A

Tbg. SI Pres.
Tbg. Inj. Pres.

Max. Inj. Pres.

Pressured annulus up to 562 psi. for 30 mins. Test passed/failed

REMARKS:

62 psi 8416
Pressure 8208
Held full 30 min test.

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

[Signature]
(Position)

Revised 02-11-02