



NEW MEXICO DEPARTMENT OF
NATURAL RESOURCES

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrds.state.nm.us/ocd/District III/3distric.htm](http://emrds.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/27/19 Operator Blackhawk Energy Corp API #30-0 39-25780
Property Name Jic 457-4 Well No. 2 Location: Unit K Section 4 Township 30N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 21 Intermediate Casing 17 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	0		17			Steady Flow	
10 min	0		17			Surges	
15 min	0		17			Down to Nothing	
20 min						Nothing	✓
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

BH showed zero on gauge and nothing through out Test.
Casing held 17 psi through out Test.
BH had zero after 5 min shut in.

By Robert Talamante
Plant/lease operator
(Position)

Witness

E-mail address rtalamante@blackhawkenergycorp.com

NM000

SEP 10 2019

DISTRICT III